




UP-APL01 active cooler assembly guide installation SOP

Presenter : Rscar Huang
Date : 2017.04.07


SOP

- Step 0 : Make sure the thermal pads are all correspondent with location of ICs shown as below




SOP

- Step 1 : Insert the cable of active cooler on the back of UP-APL01




SOP

Step 2 : Fasten the screws



SOP

- Step 3 : Done



Thank You